

015444

34010080C3

6-10270

INTER-OFFICE CORRESPONDENCE

REILLY TAR & CHEMICAL CORPORATION

TO: MR. W. A. JUSTIN - OFFICE OFFICE: St. Louis Park
FROM: Mr. H. L. Finch DATE: July 23, 1969
SUBJECT: PLANT WATER DISCHARGE

US EPA RECORDS CENTER REGION 5



514620

During my inspection with Mr. C. F. Leshar, the following items were noted that should be improved upon in connection with our plant water discharge.

1. Straw filter must be maintained in the outlet of our settling pond and please review and set up a program change of this straw filter.
2. A periodic check should be made of all clean out boxes and establish a clean out procedure.
3. The culvert going under the road, Walker Street, should be checked for clearance. The water does not seem to be flowing freely through the culvert.
4. This area should be checked generally for clean up as it can become unsightly quite rapidly.

Yours very truly,


H. L. Finch

HLF:ge

cc: Mr. W. H. Barton - Office

302800